

Inspection Photos
Location Name: Speaker - 68N61W / 27SESE
Location #: 317509



Photo #1

Speaker P (API # 05-123-05490) wellhead

Bradenhead does not appear plumbed to surface



Photo #2

Speaker P (API # 05-123-05490) Battery