

Final Reclamation Inspection

July 25, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-10803

Inspection Document #: 682403806

Weld County, CO

SESE Section 34 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON, PATRICK #1
API: 05-123-10803



Photo 1. Photo taken from the tank battery, facing North. Tank battery has an approved variance to not reclaim the tank battery location, as the surface owner is using this area for staging farming practices. No stormwater erosion or weed issues were observed at the time of this inspection.



Photo 2. Photo taken from the tank battery, facing South. See comments under Photo 1.