

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401707006

Date Received:

07/18/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: VANGUARD OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Aaron, Axelson

230-0926

aaxelson@vnrenergy.com

Ghan, Scott

970-744-8128

sghan@vnrenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689301374

Inspection Date: 06/25/2018

FIR Submit Date: 06/25/2018

FIR Status: _____

Inspected Operator Information:

Company Name: VANGUARD OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 418340

Location Name: KAUFMAN (PAD #4) Number: 43D-25-692 County: GARFIELD

Qtrqr: NWN Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.503112 Longitude: -107.604566

FACILITY - API Number: 05-045-00 Facility ID: 418333

Facility Name: Kaufman Number: 41A-25-692

Qtrqr: NWN Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.503112 Longitude: -107.604566

CORRECTIVE ACTIONS:

1 ☒ CA# 116965

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.

Date: 07/25/2018

Response: CA COMPLETED

Date of Completion: 07/17/2018

Operator
Comment:

Removed small area of stained ballast material from the lined secondary containment.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

2 ☒ CA# 116966

Corrective Action: Install sign to comply with Rule 210.e.

Date: 08/25/2018

Response: CA COMPLETED

Date of Completion: 07/17/2018

Operator Comment: Volume labels on the tank placards have been replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

3 ☒ CA# 116967

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/25/2018

Response: CA COMPLETED

Date of Completion: 07/17/2018

Operator Comment: The noted piping connection has been addressed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the Form 4 / FIRR acknowledges that the Oil and Gas Conservation Commission has received the Notice. A field inspection will be conducted to evaluate compliance.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Ghan

Signed: _____

Title: Senior EHS Specialist

Date: 7/18/2018 3:50:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401707006	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files