

Inspection Photos

API#s 103-40072 & 103-04073

Operator: Pennell Drilling

Inspection Number: 674104562

Inspection Date: 7/12/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View North over API#103-40072

May 10, 2018



Photo#2:
View South over API#103-40072



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Divide Creek API#045-09206




Photo#3:
View North over API#103-04073

May 10, 2018



Photo#4:
View South over API#103-04073



Photo#3:

Views of Open Pipe/ Casing noted approximately 30 feet to the Northeast of Well #103-04073.

Photo#4:

May 10, 2018