

**Inspection Photos**  
**Location Name: Sunmarke Tank Battery**  
**Loc ID: 323377**



**Tank battery signage**



**Tank battery site**

**Inspection Photos**  
**Location Name: Sunmarke Tank Battery**  
**Loc ID: 323377**



**Berm has eroded.**