

# Inspection Photos

07/26/2018

Operator: PAR PACIFIC HOLDINGS INC - 16800

Location ID: 404554

Inspection Doc. Number: 682503668

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the west end of the location, facing northeast. Photos 1-3 provide an overview of the location and the vegetation over the reclamation area from northeast, east, to southeast. . Vegetation appears to have achieved sufficient uniform desirable perennial vegetative cover reflective of the reference.



**Photo 2:**





**Photo 3:**



**Photo 4:** Photo taken from the west end of the location. Photo shows pipe riser remaining on location. Riser needs to be removed in accordance to 1004.a



Inspection Photos  
Operator: PAR PACIFIC HOLDINGS INC - 16800  
Location ID: 404554



**Photo 5:** Photo taken from the west end of the location. Photo shows pipe riser remaining on location. Riser needs to be removed in accordance to 1004.a



**Photo 6:** Photo taken from the access road, west of the location (GPS coordinates 39.77372/-102.88281). Photo shows pipe riser equipment remaining. Riser needs to be removed in accordance to 1004.a