



00054090

WELL SITE INSPECTION FORM

Well Name Marick 1 API Number 05 - 121 - 7094
Operator Bermergen Corp Permit # 840903
Location SESE2 2N 52 County Washington
Field _____ Inspector Binkley
AL/PA/DA Inspection Results: Well Status:
Pass (Y) _____ Fail (N) X Date 7-24-90 FN _____ FD _____ WO _____ PR _____ SI _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Contact _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 4-24-89 Date Permit Expired: _____
Hole Plugged: Yes ✓ No _____ Pits Backfilled: Yes _____ No ✓
Material Buried: Yes _____ No ✓ N/A _____ Site Clean: Yes _____ No ✓
Bond Release OK: Yes _____ No ✓ Fed _____ Hole Marker: Yes _____ No ✓

Date of Safety/Status Inspection _____

Comments: No action at reclamation to date.

H&R has not completed work per agreed upon
time. File forwarded to Jim Kenney 7-31-90.
E

Violations: Yes ✓ No _____ Notice Sent: Yes _____ No _____ Date Sent: 11-16-89
5-17-91

295-2323

ROY WHITE

Called & Asked for RETURN CALL.
8/1/90 - RETURN CALL BY MR WHITE, WILL
LOOK INTO IT & LET US KNOW WHEN IT
IS CLEANED UP.

JSL.