

Inspection Photos  
Location Name: GUADAGNOLI #1  
Facility ID: 240510



Photo 1. Wellhead **Corrective actions: Weeds around wellhead cannot see sign, fence is down on wellhead side of pump jack.**



Photo 2. Tank battery



Inspection Photos  
Location Name: GUADAGNOLI #1  
Facility ID: 240510



**Photo 3. Fence around tank battery.**  
**Corrective action: fence down**



**Photo 4. Corrective action: Weeds around  
produced water tank.**