

**Inspection Photo
MCU 32-7 (G32E)
API # 045-14084
Inspection # 689301608**



Location Photo #1



Location Photo #2, Hole in containment liner

**Inspection Photo
MCU 32-7 (G32E)
API # 045-14084
Inspection # 689301608**



Location Photo #3, Hole in containment liner



Location Photo #4, Hole in containment liner