

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401699603  
Receive Date:  
07/31/2018

Report taken by:  
PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATON

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Phil Hamlin</u>	Email: <u>Phil.Hamlin@anadarko.com</u>	Mobile: <u>( )</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 4013 Initial Form 27 Document #: 1881343

PURPOSE INFORMATION

- 901.e. Sensitive Area Determination
- 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
- 909.c.(1), Rule 905: Pit or PW vessel closure
- Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
- 909.c.(2), Rule 906: Spill/Release Remediation
- Rule 909.e.(2)B.: Closure of remediation project
- 909.c.(3), Rule 907.e.: Land treatment of oily waste
- Rule 906.c.: Director request
- 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure
- Other \_\_\_\_\_

SITE INFORMATION

N Multiple Facilites ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>317962</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>SARCHET LAURA A GAS UNIT-63N66W 21SWNE</u>		Latitude: <u>40.213190</u>	Longitude: <u>-104.778760</u>
		** correct Lat/Long if needed: Latitude: <u>40.212829</u>	Longitude: <u>-104.778799</u>
QtrQtr: <u>SWNE</u>	Sec: <u>21</u>	Twp: <u>3N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Agriculture

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Excavation groundwater approximately 16 feet (ft) below ground surface (bgs).

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See Attached Data	Groundwater Samples/Lab Analysis
Yes	SOILS	90' N-S x 50' E-W x 23' bgs (max)	2007/2008 Excavations - Soil Samples/Lab Analysis

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In May 2007, soil with historical petroleum hydrocarbon impacts was encountered while tying new wells into the Sarchet 24, 21-21/Sarchet Laura A GU #1 tank battery. The wells were shut in and petroleum hydrocarbon impacted soil was excavated.

In November 2008, an operator left the production tank drain valve open to the water sump and left the site. Approximately 80 barrels of crude oil were released within the steel tank battery berm before the night operator arrived and closed the drain valve. A vacuum truck was used to recover 35 barrels of crude oil from inside the berm and the petroleum hydrocarbon impacted soil was excavated. The Site Map depicting the 2007 and 2008 excavations is attached as Figure 1.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Please refer to the Form 27 for the 2007 release submitted to the COGCC on September 17, 2007, and the Form 27 for the 2008 release submitted to the COGCC on March 17, 2009.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Quarterly groundwater monitoring has been conducted at the site since August 2007.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 15  
Number of soil samples exceeding 910-1 3  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 4000

### NA / ND

-- Highest concentration of TPH (mg/kg) 7200  
NA Highest concentration of SAR           
BTEX > 910-1 No  
Vertical Extent > 910-1 (in feet) 12

### Groundwater

Number of groundwater samples collected 625  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 3'  
Number of groundwater monitoring wells installed 25  
Number of groundwater samples exceeding 910-1 325

-- Highest concentration of Benzene (µg/l) 15000  
-- Highest concentration of Toluene (µg/l) 12000  
-- Highest concentration of Ethylbenzene (µg/l) 1100  
-- Highest concentration of Xylene (µg/l) 15000  
NA Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected  
         Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Groundwater impacts were detected in the agricultural field northeast of the tank battery.

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)          Volume of liquid waste (barrels)         

Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please refer to the Form 27 for the 2007 release submitted to the COGCC on September 17, 2007, and the Form 27 for the 2008 release submitted to the COGCC on March 17, 2009.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the Form 27 for the 2007 release submitted to the COGCC on September 17, 2007, and the Form 27 for the 2008 release submitted to the COGCC on March 17, 2009.

## Soil Remediation Summary

In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

Ex Situ

Yes \_\_\_\_\_ Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 2013

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_ 149007

No \_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

Yes \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

No \_\_\_\_\_ Chemical oxidation

No \_\_\_\_\_ Air sparge / Soil vapor extraction

Yes \_\_\_\_\_ Natural Attenuation

Yes \_\_\_\_\_ Other Groundwater Removal and  
MicroBlaze® Application \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater monitoring wells MW01R through MW04, MW07 through MW13, TMW01, TMW05, and TMW10 are sampled on a quarterly basis and submitted for laboratory analysis for benzene, toluene, ethylbenzene, and total xylenes (BTEX) by United States Environmental Protection Agency (USEPA) Method 8260C. The monitoring well locations are depicted on Figure 1. The Groundwater Elevation Contour Map generated using the April 2017 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical report for the April 2017 groundwater monitoring event is attached.

Groundwater and surface water monitoring will continue on a quarterly basis until a No Further Action status request is warranted.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

The petroleum hydrocarbon impacted soil was transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado, for recycling.

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 2013

E&P waste (solid) description Petroleum hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_ 149007

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 40

E&P waste (liquid) description Petroleum hydrocarbon impacted groundwater

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_ 159255

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No \_\_\_\_\_

Do all soils meet Table 910-1 standards? Yes \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? No \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? No \_\_\_\_\_

Is additional groundwater monitoring to be conducted? Yes \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site was restored to its pre-release grade. The Kerr-McGee's production facility remains at the site.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. 05/07/2007

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/09/2007

Date of commencement of Site Investigation. 05/07/2007

Date of completion of Site Investigation. 10/28/2016

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 05/07/2007

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin

Title: Senior HSE Representative

Submit Date: 07/31/2018

Email: Phil.Hamlin@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 07/31/2018

Remediation Project Number: 4013

### COA Type

### Description

<u>COA Type</u>	<u>Description</u>
	Submit reports of site investigation and progress of remediation including results of sampling and analysis on an annual basis or more often until remediation is closed.

### Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

<u>Att Doc Num</u>	<u>Name</u>
401699603	FORM 27-SUPPLEMENTAL-SUBMITTED
401699656	ANALYTICAL RESULTS
401703502	SITE MAP
401703503	GROUND WATER ELEVATION MAP

Total Attach: 4 Files

### General Comments

### User Group

### Comment

### Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)