

Final Reclamation Inspection

July 25, 2018

Operator: SRC ENERGY INC- #10311

API: 05-123-12392

Inspection Document #: 682403818

Weld County, CO

SWNE Section 13 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MOORE #2
API: 05-123-12392



Photo 1. Photo taken from the tank battery location, facing North. No visual evidence of equipment on location.

Inspection Photos
Location Name: MOORE #2
API: 05-123-12392



Photo 2. Photo taken from the well location, facing East. Well location will remain in-process until it meets Rule 1004 vegetative standards, as uniform vegetative has not established.



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: MOORE #2
API: 05-123-12392



Photo 4. Reference photo taken south of the well location, facing South.