

Inspection Photos  
Location Name: Latin 33-12  
API: 05-081-06898



**Photo 1. Overview of location taken at entrance facing northwest.**

Inspection Photos  
Location Name: Latin 33-12  
API: 05-081-06898



Photo 2. Unused tank stored on location.



Photo 3. Unused tank labeled "permanently closed."