

Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Photo #1

Federal North Wildhorse 7-28 (API # 05-123-12824)

wellhead view 1

Bradenhead not plumbed to surface



Photo #2

Federal North Wildhorse 7-28 (API # 05-123-12824)

wellhead view 2



Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Photo #3

Federal North Wildhorse 7-28 (API # 05-123-12824)

Battery



Photo #4

Federal North Wildhorse 7-28 (API # 05-123-12824)

Pit



Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292




Photo #5

Federal North Wildhorse 7-28 (API # 05-123-12824)

Unmarked Risers



Photo #6

Federal North Wildhorse 7-28 (API # 05-123-12824)

Pumpjack gearbox & soil stain



Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Photo #7

Federal North Wildhorse 7-28 (API # 05-123-12824)

Pumpjack skid stained soil



Photo #8

Federal North Wildhorse 7-28 (API # 05-123-12824)

Gas Engine area stained soil



Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Photo #9

Federal North Wildhorse 7-28 (API # 05-123-12824)

Pumpjack gas engine exhaust stained soil

