

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2018

Submitted Date:

07/31/2018

Document Number:

689100171

FIELD INSPECTION FORM

Loc ID 434526 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	PR	11/01/2017	OW	123-38225	Pratt 4G-29H-P168	PR
434527	WELL	PR	12/01/2017	OW	123-38226	Pratt 4D-29H-P168	PR
434528	WELL	PR	12/01/2017	OW	123-38227	Pratt 4F-29H-P168	PR
434529	WELL	PR	12/01/2017	OW	123-38228	Pratt 4E-29H-P168	PR
434530	WELL	PR	12/01/2017	OW	123-38229	Pratt 4B-29H-P168	PR
434733	WELL	PR	12/01/2017	OW	123-38301	Pratt 4C-29H-P168	PR

General Comment:

Inspected Facilities

Facility ID: <u>434525</u>	Type: <u>WELL</u>	API Number: <u>123-38225</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434527</u>	Type: <u>WELL</u>	API Number: <u>123-38226</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434528</u>	Type: <u>WELL</u>	API Number: <u>123-38227</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434529</u>	Type: <u>WELL</u>	API Number: <u>123-38228</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434530</u>	Type: <u>WELL</u>	API Number: <u>123-38229</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434733</u>	Type: <u>WELL</u>	API Number: <u>123-38301</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Complaint

Comment: [Field Inspector Assigned: Jason E. Gomez](#)

[Complaint Received:](#)

[Date: 3-26-2018](#)

[Complaint Contacted:](#)

[Date: 3-26-2018 Time 1400 Hrs](#)

[Location #: 434526](#)

[Inspection Document #: 689100171](#)

[Nature of complaint: Noise](#)

[Field Inspector Actions:](#)

[On 3-26-2018, I was contacted by COGCC staff in reference to some complaints received by the COGCC in reference to noise, and possible gas leak occurring in the Erie area originating from the Extraction, Coyote location.](#)

[On 3-26-2018, I attempted to contact the complainant. I performed a sit inspection and I contacted Crestone's central hub which monitors the prat location with laser gas leak detection equipment to alert them of any leaks at the Pratt location. The Crestone Hub did not show any gas leaks at the location nor were any leaks found at the time of the inspection](#)

[No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

Corrective Action:

Date: