



Photo 1. View of the reclaimed well pad area from the western corner facing center. Location is revegetated and fence removed.



Photo 2. View of the northwestern portion of the project area from the western corner facing northeastward.



Photo 3. View of the southern portion of the project area from the western corner facing eastward.



Photo 4. View of the recently reclaimed access road. Some desirable vegetation was observed.



Photo 4. View of sample quadrat number “2”. Eight desirable seedlings were counted in this quadrat.



Photo 4. View of sample quadrat number “4”. Five desirable seedlings were counted in this quadrat.