

Inspection Photos

07/31/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312228

Inspection Doc. Number: 682503674
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312228



Photo 1: Photo taken from the east end of the location, facing north. Photo shows pipe equipment and barrels laying on the ground. Pipe is unused equipment not needed for production and needs to be removed and properly stored. Barrels need to be placed in secondary containment or removed and properly stored.



Photo 2: See comments under photo 1.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312228



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the west end of the location, facing northeast. Photo shows plastic chemical container. Container needs to be placed in secondary containment or removed and properly stored.