

Inspection Photos
Location Name: Visintainer Federal 1-12
API: 05-081-07045



Photo 1. Overview of location taken at entrance facing southwest.

Click here to read the form

State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Well Number: 21112
Test Date: 8/1/18
Pressure: 470 psi
Test Interval: 1800 ft

Tested by: Brian Rogers
Witnessed by: [Signature]
Date: 8/1/18

Inspection Number: 689801485

Photo 2. Photo of Form 21 as witnessed and signed in the field.

Inspection Photos
Location Name: Visintainer Federal 1-12
API: 05-081-07045



Photo 3. Gauge hatch open, incorrect emergency contact on signs.



Photo 4. Example of noxious weeds on location.