

Inspection Photos
Location Name: Visintainer 11-6-8-90
API: 05-081-07239



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Visintainer 11-6-8-90
API: 05-081-07239



Photo 2. Incorrect emergency contact information on location signs.



Photo 3. Incorrect emergency contact information on location signs.