

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2018

Submitted Date:

08/01/2018

Document Number:

689100172

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319094 _____ Gomez, Jason _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453223	WELL	DG	02/05/2018		123-45983	Coyote Trails 34S-20-12N	WO
453224	WELL	DG	02/04/2018		123-45984	Coyote Trails 34S-20-14N	WO
453225	WELL	DG	03/28/2018		123-45985	Coyote Trails 34S-20-9N	WO
453226	WELL	DG	02/27/2018		123-45986	Coyote Trails 34S-20-8N	WO
453227	WELL	DG	02/03/2018		123-45987	Coyote Trails 34S-20-15C	WO
453229	WELL	DG	03/27/2018		123-45989	Coyote Trails 33S-20-7C	WO
453230	WELL	DG	02/03/2018		123-45990	Coyote Trails 34S-20-16N	WO
453231	WELL	DG	02/05/2018		123-45991	Coyote Trails 34S-20-11C	WO
453233	WELL	DG	02/04/2018		123-45993	Coyote Trails 34S-20-13N	WO
453234	WELL	DG	02/06/2018		123-45994	Coyote Trails 34S-20-10N	WO

General Comment:

Inspected Facilities

Facility ID: <u>453223</u>	Type: <u>WELL</u>	API Number: <u>123-45983</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453224</u>	Type: <u>WELL</u>	API Number: <u>123-45984</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453225</u>	Type: <u>WELL</u>	API Number: <u>123-45985</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453226</u>	Type: <u>WELL</u>	API Number: <u>123-45986</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453227</u>	Type: <u>WELL</u>	API Number: <u>123-45987</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453229</u>	Type: <u>WELL</u>	API Number: <u>123-45989</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453230</u>	Type: <u>WELL</u>	API Number: <u>123-45990</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>453231</u>	Type: <u>WELL</u>	API Number: <u>123-45991</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

Complaint

Comment:

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 6-26-2018

Complaint Contacted:

Date: 6-26-2018 Time 0900 Hrs

Location #: 319094

Inspection Document #: 689100172

Nature of complaint: Odors/Noise

Field Inspector Actions:

On 6-22-2018 through 6-26-2018, I observed the COGCC was receiving some complaints of odors from the Erie area. The complaint stated the odors were coming from what they thought was the Extraction, Coyote location.

During the weekend of 6-23-2018 through 6-25-2018 I wen through the neighborhood of the complaints residence several times at no time did I ever detect odors in the neighborhood.

On 6-26-2018, I attempted to contact the complaints in reference to the odors they were experiencing which they perceived as coming from the Coyote location. I went to the Extraction Coyote location and I observed that there were no personal or equipment on location. I contacted Extraction who was in flow back operations at location Extraction where changing out tank at the time of the inspection to mitigation of odors comin from location.

No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Facility ID: 453233 Type: WELL API Number: 123-45993 Status: DG Insp. Status: WO

Facility ID: 453234 Type: WELL API Number: 123-45994 Status: DG Insp. Status: WO