

**Inspection Photo**  
**Kaufman 32D-25-692**  
**API # 045-21145**  
**Inspection # 689301644**



**Location Photo #1**




**Location Photo #2**

**Inspection Photo**  
**Kaufman 32D-25-692**  
**API # 045-21145**  
**Inspection # 689301644**



**Location Photo #3**



**Location Photo #4, Stained/oily rock in  
corner of containment by stairs**



**Inspection Photo**  
**Kaufman 32D-25-692**  
**API # 045-21145**  
**Inspection # 689301644**



**Location Photo #5, Stained/oily rock in corner  
of containment by stairs**