

CHEVRON TR 41-35-597

API# 05-045-06606

Inspection# 689701683



Location photo.

CHEVRON TR 41-35-597

API# 05-045-06606

Inspection# 689701683



Hydrocarbons observed on pit.

CHEVRON TR 41-35-597

API# 05-045-06606

Inspection# 689701683



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

CHEVRON TR 41-35-597
API# 05-045-06606
Inspection# 689701683



Diesel fuel tank.

CHEVRON TR 41-35-597
API# 05-045-06606
Inspection# 689701683



Spillage inside of secondary containment.



Spillage outside of secondary containment.

CHEVRON TR 41-35-597

API# 05-045-06606

Inspection# 689701683



Unused poly pipe