

**Inspection Photo
River Ranch B1
API # 045-10848
Inspection # 689301660**



Location Photo #1, Weeds along edge of location near ECB



Location Photo #2, Weeds near Pig station.

**Inspection Photo
River Ranch B1
API # 045-10848
Inspection # 689301660**



Location Photo #3, weeds on location.



Location Photo #4, Unmarked flow lines

**Inspection Photo
River Ranch B1
API # 045-10848
Inspection # 689301660**



Location Photo #5, Weeds in reclaimed area



Location Photo #6, Weeds in reclaimed berm area.