

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2018

Submitted Date:

08/03/2018

Document Number:

692600068**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 304498 Welsh, Brian 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa | | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 263177 | WELL | PR | 05/31/2007 | GW | 125-08623 | STALLINGS 21-12 | PR |

General Comment:[Routine Inspection](#)

Location

| | | | |
|--------------------|-----------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | Date: | | |

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit, wellhead, VGS and meter run | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Kohler gas engine | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator 50% buried by meter run | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Gas scrubber and telemetry equipment | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 263177 | Type: | WELL | API Number: | 125-08623 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT