

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401694843
Date Received:
07/06/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ghan, Scott	970-744-8128	sghan@vnrenergy.com
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689301463
Inspection Date: 07/05/2018 FIR Submit Date: 07/05/2018 FIR Status:

Inspected Operator Information:

Company Name: VANGUARD OPERATING LLC Company Number: 10531
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 322510

Location Name: MOBILE-66S92W Number: 20NESW County: GARFIELD
Qtrqtr: NESW Sec: 20 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.509476 Longitude: -107.693676

FACILITY - API Number: 05-045-00 Facility ID: 210663

Facility Name: MOBILE Number: 11-20
Qtrqtr: NESW Sec: 20 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.509476 Longitude: -107.693676

CORRECTIVE ACTIONS:

1 CA# 117213

Corrective Action: Install sign to comply with Rule 210.e. Date: 09/05/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Findings are inappropriately tied to multiple wells

Operator Comment: The sign is legible and in compliance with Rule 210.e, as seen in the inspection photos. The tank placard could have been noted on the FIR, but did not need to be listed as a CA. Vanguard Operating will replace the tank placard, but we have seen several of these unwarranted CAs recently related to tank placards.

COGCC Decision: **Not Approved**

COGCC Representative:

[Empty text box for COGCC Representative]

COGCC Supervisor:

Location 322510 is a single well pad. Review of database only shows one permitted well 045-06419. FIR Doc # 689301463 is correctly applied to the production tank battery serving the single well on the specified location.

2  CA# 117214

Corrective Action:

Comply with Rule 603.f .

Date: 11/05/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment belongs to the surface owner

Operator Comment:

This derelict RV has been discussed multiple times in relation to COGCC inspections. Please see the attached email response from former COGCC Director Matt Lepore regarding the RV. Vanguard requests that the COGCC file the attached correspondence in the inspection record, so that this topic resurface in future inspections.

COGCC Decision: **Not Approved**

COGCC Representative:

[Empty text box for COGCC Representative]

COGCC Supervisor:

Stored RV on Location 322510 is partially on the permitted pad surface. Stored RV is close enough to cause a safety and fire hazard to production equipment on location. Stored RV is positioned in a manner that is causing stormwater, and reclamation issues. Debris from the stored RV are lying on the pad surface.

OPERATOR COMMENT AND SUBMITTAL

Comment:

Please note attachment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Ghan

Signed: _____

Title: Senior EHS Specialist

Date: 7/6/2018 7:32:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401694843	FIR RESOLUTION SUBMITTED
401694849	Email Correspondence

Total Attach: 2 Files