

# Inspection Photos

08/02/2018

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 319759

Inspection Doc. Number: 682503698  
Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319759



**Photo 1:** Photo taken from the southwest corner of the former battery location, facing north. Photo shows battery location remains predominantly undesirable weedy plant species such as Kochia and Russian thistle, as well as noxious weeds such as Canada Thistle. Very little desirable perennial vegetative germination and establishment is evident.



**Photo 2:** Photo taken from the southwest corner of the former battery location, facing east. Photo shows battery location remains predominantly undesirable weedy plant species such as Kochia and Russian thistle, as well as noxious weeds such as Canada Thistle. Very little desirable perennial vegetative germination and establishment is evident.

Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 319759



**Photo 3:** Photo taken from within the former battery location. Photo shows battery location remains predominantly undesirable weedy plant species such as Kochia and Russian thistle, as well as noxious weeds such as Canada Thistle (yellow arrow). Very little desirable perennial vegetative germination and establishment is evident.



**Photo 4:** Photo taken from the west end of the former battery location, facing east. Photo shows battery location remains predominantly undesirable weedy plant species such as Kochia and Russian thistle, as well as noxious weeds such as Canada Thistle (yellow arrow). Very little desirable perennial vegetative germination and establishment is evident.