

Inspection Photos

08/02/2018

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 376781

Inspection Doc. Number: 682503706
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 1: Photo taken from the northeast corner of the pad, facing west. Photo shows reclamation in process.



Photo 2: Photo taken from the northeast corner of the pad, facing south. Photo shows reclamation in process.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 3: Photo taken from the area of the well on the east end of the pad, facing west. Photo shows very little desirable perennial germination observed in these areas. Additional revegetation activities may be needed.



Photo 4: Photo taken from the area of the well on the east end of the pad. Photo shows very little desirable perennial germination observed in these areas. Additional revegetation activities may be needed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 5: Photo taken from the south end of the fenced spill area, facing northwest. Photo shows additional reclamation activities appear to have been conducted.



Photo 6: Photo taken from the south end of the fenced spill area, facing north. Photo shows additional reclamation activities appear to have been conducted.