

Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671



Location Photo #1,



Location Photo #2



**Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671**



Location Photo #3, Weeds on location.



Location Photo #4, Weeds on location.

**Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671**



Location Photo #5, Weeds on location.



Location Photo #6, Weeds on location.

**Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671**



Location Photo #7, Stained rock in battery containment.



Location Photo #8, Stained rock in battery containment.

**Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671**




Location Photo #9, Stained rock in battery containment.



Location Photo #10, Stained rock in battery containment.

**Inspection Photo
Magnall 34-12 (L34)
API # 045-09156
Inspection # 689301671**



Location Photo #11, Stained rock in battery containment.



Location Photo #12, Stained rock in battery containment.