

**Inspection Photo  
Bell 34-4C (D34NE)  
API # 045-10129  
Inspection # 689301683**



**Location Photo #1**



**Location Photo #2,**

**Inspection Photo**  
**Bell 34-4C (D34NE)**  
**API # 045-10129**  
**Inspection # 689301683**



**Location Photo #3, Stained rock in tank containment.**




**Location Photo #4, Stained rock in tank containment.**



**Inspection Photo  
Bell 34-4C (D34NE)  
API # 045-10129  
Inspection # 689301683**



**Location Photo #5, Stained rock in tank containment.**



**Location Photo #6, Holes in secondary containment.**



**Inspection Photo  
Bell 34-4C (D34NE)  
API # 045-10129  
Inspection # 689301683**



**Location Photo #7, Holes in secondary containment.**



**Location Photo #8, Holes in secondary containment.**