

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/02/2018

Submitted Date:

08/05/2018

Document Number:

688302324

FIELD INSPECTION FORM

Loc ID 449179 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
Address: 600 N DAIRY ASHFORD RD
City: HOUSTON State: TX Zip: 77079

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Yu, Liang	281-467-5712	Liang.Yu@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449177	WELL	DG	07/23/2018		001-10004	Bear 3-65 22-23 3AH	DG

General Comment:

[BOP](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 449177 Type: WELL API Number: 001-10004 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Nabors B16 Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: YES
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Shell Test, Annular low 250, high 5000.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302328	Burlington Resources Oil & Gas LP, Bear 3-65 22-23 3AH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4543697