

Inspection Photos
Well Name: NVega 3A Pad
Location ID: 334487



Photo 1. Missing LOTO tags.



Photo 2. Missing LOTO tags.