

Inspection Photos
Location Name: NVega 5B Pad
Location ID: 334466



Photo 1. Location.



Photo 2. Out of service tank in containment.