

Inspection Photos

API#103-09161

Operator: Bayswater

Inspection Number: 674104582

Inspection Date: 7/13/2018





Photo#1:

View over Location from Entry to West. There are large areas bare of vegetation.

July 13, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater PA Emerald API#103-09161



Photo#2:

Disturbance created by removal of Concrete will be addressed by Reclamation activities.

July 13, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater PA Emerald API#103-09161



Photo#3:
Long & close up view of Vegetation in Location area.

July 13, 2018



Photo#4:



Photo#5:
Long & close up view of Vegetation in Reference area.



Photo#6:

July 13, 2018