

Inspection Photos

Location Name: Sooner Unit - 68N58W / 16SWSW

Location #: 323740



Photo #

Sooner Unit 13-16 (API # 05-123-13452) wellhead

Bradenhead NOT plumbed to surface

Unused equip – Waste at wellsite



Photo #2

Sooner Unit 13-16 (API # 05-123-13452) wellsite

New sign has been posted.

Fence has been repaired.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources