

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2018

Submitted Date:

08/06/2018

Document Number:

688302336

FIELD INSPECTION FORM

Loc ID 453036 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35080
Name of Operator: GRAND MESA OPERATING CO
Address: 1700 N. WATERFRONT PKWY BL 600
City: WICHITA State: KS Zip: 67206

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Reilly, Pat	316-265-3000	preilly@gmocks.com	
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453035	WELL	DG	08/06/2018		073-06733	YOSEMITE 1-3	DG

General Comment:

[Surface Cementing/BOP Inspection](#)

Inspected Facilities

Facility ID: 453035 Type: WELL API Number: 073-06733 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: WW Drilling Rig 20 Pusher/Rig Manager: Sammy
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 800 Safety Plan: YES

Drill Fluids

Management:

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
 Multi-Well: NO Disposal Location: on location

Comment: BOP low 200 psi
Surface TD 357'
Surface pipe, 8 5/8" at 355'

Corrective Action: _____ Date: _____

Cement

Cement Contractor

Contractor Name: QES Contractor Phone: _____

Surface Casing

Cement Volume (sx): 325 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: 1 am

Corrective Action: _____ Date: _____