

Inspection Photos  
Well Name: Oxbow 18-1E  
Location ID: 312634



**Photo 1. Halogeton, Class 3 Noxious Weed along edge and in middle of access road.**



**Photo 2. Halogeton, Class 3 Noxious Weed along edge and in middle of access road.**

Inspection Photos  
Well Name: Oxbow 18-1E  
Location ID: 312634



Photo 3. Wellhead.



Photo 4. Erosion and sediment migration along perimeter of location.