

**Inspection Photos**  
**Location Name: HSR-SEEWALD #11-31**  
**API: 05-123-18725**



**Weeds by tank before completed CA**



**Weeds by separator before completed CA**

Inspection Photos  
Location Name: HSR-SEEWALD #11-31  
API: 05-123-18725



Weeds removed. CA completed.



Weeds removed. CA completed.