

Inspection Photos
Location Name: McCallum Unit 120
API: 05-057-06342



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Stained soil at wellhead.