

**Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705**



Location Photo #1,



Location Photo #2,



Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705



Location Photo #3,



**Location Photo #4, unused equipment,
south end tank battery.**

**Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705**



Location Photo #5, stained soil at well heads.



Location Photo #6, stained soil near wellheads.



**Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705**



**Location Photo #7, Weeds in interim
reclamation, west side of location**



**Location Photo #8, Weeds in interim
reclamation, west side of location**



**Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705**



Location Photo #9, Weeds in interim reclamation, southern slope above tanks.



Location Photo #10, Weeds in interim reclamation

Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705



Location Photo #11, Weeds in interim reclamation



Location Photo #12, Weeds in interim reclamation, southern slope

**Inspection Photo
Youberg SR 443-12
API # 045-18422
Inspection # 689301705**



Location Photo #13, Weeds in interim reclamation, southern slope.



Location Photo #14, Weeds in interim reclamation, near gates