

Inspection Photos

Location Name: Maynard Water Well Sampling, COGCC Complaint #200446120

Inspection Date: 8/9/2018



Photo 1 – Water well location looking northeast at Highway 14 and spill area (plastic sheets) in distance.



Photo 2 – Water well and hydrant viewing northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Maynard Water Well Sampling, COGCC Complaint #200446120

Inspection Date: 8/9/2018



Photo 3 – Sample collection at Maynard Water Well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources