

Inspection Photos

Location Name: Sandridge Exploration and Production, Poudre Canyon Spill, Spill ID 456513

Inspection Date: 8/9/2018



Photo 1 – Area of crash and spill area covered with plastic sheeting. Looking east down-canyon.



Photo 2 – At driveway of 9552 W Hwy 14, looking west up-canyon.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandridge Exploration and Production, Poudre Canyon Spill, Spill ID 456513

Inspection Date: 8/9/2018



Photo 3 – At driveway of 9552 W Hwy 14, looking east down-canyon.



Photo 4 – From end of spill path, looking west up-canyon.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources