

# Final Reclamation Inspection

July 26, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 333045

Inspection Document #: 682403836

Weld County, CO

SWSE Section 31 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: LOWE-66N66W /31SWSE

Location ID: 333045



**Photo 1.** Photo taken from the central location, facing West. Appears the Operator has performed final reclamation activities; however, the location has not been contoured to match the surrounding landscape. No equipment was observed at the location. Germination was observed with patches of bare soil and will remain in-process until the location meets Rule 1004 standards.

Inspection Photos

Location Name: LOWE-66N66W /31SWSE

Location ID: 333045



**Photo 2.** Photo taken from the central location, facing South. See comments under Photo 1.

Inspection Photos

Location Name: LOWE-66N66W /31SWSE

Location ID: 333045



**Photo 3.** Photo taken of the eastern location, facing North. See comments under Photo 1.

Inspection Photos

Location Name: LOWE-66N66W /31SWSE

Location ID: 333045



**Photo 4.** Photo taken of the northern location, facing North. See comments under Photo 1.