

# Final Reclamation Inspection

July 26, 2018

Operator: SRC ENERGY INC- #10311

API: 05-123-24463

Inspection Document #: 682403838

Weld County, CO

SWSW Section 31 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: LOWE #31-14  
API: 05-123-24463



**Photo 1.** Photo taken from the tank battery location, facing West. Appears the Operator has performed final reclamation activities. No equipment was observed at the battery location. Vegetative assessment was only conducted at the battery location, not the well location or well access road. Does not appear the location was planted with reference crops. Location will remain in-process until the location meets Rule 1004 standards.

Inspection Photos  
Location Name: LOWE #31-14  
API: 05-123-24463



**Photo 2.** Photo taken from the central tank battery location, facing West. See comments under Photo 1.