

# Inspection Photos

08/10/2018

Operator: CHANDLER & ASSOCIATES LLC - 15850

Location ID: 378092

Inspection Doc. Number: 682503714

Arapahoe County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: CHANDLER & ASSOCIATES LLC - 15850  
Location ID: 378092



**Photo 1:** Photo taken from the southwest end of the location, facing north. Photo shows vegetation over the reclamation area. At least two growing seasons have passed since additional reclamation activities have been conducted. Vegetation appears to be establishing well and reclamation appears to be in process.



**Photo 2:** Photo taken from the southwest end of the location, facing northeast. Photo shows vegetation over the reclamation area. See comments under photo 1.



Inspection Photos  
Operator: CHANDLER & ASSOCIATES LLC - 15850  
Location ID: 378092



**Photo 3:** Photo taken from the north end of the location, facing south. Photo shows vegetation over the reclamation area. See comments under photo 1.



**Photo 4:** Photo taken from the north end of the location, facing east. Photo shows vegetation over the reclamation area. See comments under photo 1.