

Inspection Photos
Location Name:Ruebel #1-2
Location ID: 446472



Photo#1Production Tank and Produced Water Pit
Corrective Action Uncontrolled Weeds

Photo#2Separator/Gas Meter
Corrective Action Uncontrolled Weeds

Inspection Photos
Location Name:Ruebel #1-2
Location ID: 446472



Photo#3 Corrective Action Uncontrolled Weeds

Photo#4 Corrective Action Uncontrolled Weeds