

Reclamation and Stormwater Inspection

July 30, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 455340

Inspection Document #: 682403841

Weld County, CO

SESE Section 18 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rinn Valley West
Location ID: 455340



Photo 1. Photo taken from the entrance of location off CR 20.5, facing South. Operator has installed tracking device BMPs and appears to be in proper functioning condition.



Photo 2. Photo taken from the entrance of location, facing North. Ditch and berm BMP has been installed around the entire perimeter of the location.

Inspection Photos
Location Name: Rinn Valley West
Location ID: 455340



Photo 3. Photo taken of the eastern fill slope, facing West. Photo illustrates rill erosion. Operator shall stabilize fill slopes to minimize site degradation.



Photo 4. Photo taken from the outlet area of the northeast sediment trap, facing West. No sediment discharge was observed. Operator also has a retention area, not shown in this photo, upslope from this sediment trap.

Inspection Photos
Location Name: Rinn Valley West
Location ID: 455340



Photo 5. Photo taken from the northeast perimeter of the location, facing South. Photo illustrates a stabilized outfall from the retention pond which is directed to the sediment trap previously shown in Photo 4.



Photo 6. Photo taken from the northern sediment trap, facing South. No sediment discharge was observed.

Inspection Photos
Location Name: Rinn Valley West
Location ID: 455340



Photo 7. Photo taken from the northern perimeter of the location, facing West. Photo illustrates a ditch and berm BMP and the topsoil stockpile.



Photo 8. Photo taken from the northwestern perimeter of the location, facing East. Topsoil stockpile has been stabilized with equipment tracking and appears to be seeded. Germination was observed along portions of the topsoil stockpile.

Inspection Photos
Location Name: Rinn Valley West
Location ID: 455340



Photo 9. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 2.



Photo 10. Photo taken from the southeast perimeter of the location, facing North. See comments under Photo 2.