



**Photo 1. View of the project area from the southeastern corner facing center.**





**Photo 2. View of the southeastern portion of the project area from the southeastern corner facing southwestward. Vegetation such as western wheatgrass (*Pascopyrum smithii*) is established.**





**Photo 3. View of the northeastern portion of the project area from the southeastern corner facing northwestward.**



**Photo 4. View of the southwestern portion of the project area from the southwestern corner facing northwestward.**





**Photo 5. View of debris on the well pad.**



**Photo 6. View of more debris in the southeastern cut-slope.**





**Photo 5. View unused equipment within the project area.**