

Inspection Photos

API#045-06376

Operator: Maralex

Inspection Number: 692400002

Inspection Date: 7/31/2018





Photo#1:
Overview of Location from entry to West. Note Knapweed circled in red.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



Photo#2:

There are holes in netting that is layered on panels, allowing ingress of smaller Wildlife, who even though Pit is dry at this time would not be able to find egress.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



Photo#3:

In Interim reclamation, areas of original disturbance and invading into adjacent lands is an established mono-culture of Knapweed.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376