

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2018

Submitted Date:

08/14/2018

Document Number:

692600088

**FIELD INSPECTION FORM**

Loc ID 311029 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10489  
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC  
Address: 2016 GRAND AVENUE #A  
City: BILLINGS State: MT Zip: 59102

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298098	WELL	PR	01/28/2009	GW	125-11422	CHAPMAN 19-10	PR

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease signs at meter sheds		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Maintain weeds on access and around location at unit and meter sheds		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Metal panels around meter sheds and VGS		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 2		corrective date
Comment:	Electric panel and telemetry equipment at meter sheds		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators 50% buried by meter sheds 2110' NE of wellhead		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for (Chapman 19-10 and 19-11) 2110' NE of wellhead		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 298098 Type: WELL API Number: 125-11422 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Chapman 19-10 and 19-11\) 2110' NE of wellhead on west side of CR BB](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT