

# Final Reclamation Inspection

July 30, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-19595

Inspection Document #: 682403865

Weld County, CO

NWNW Section 10 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR-STREAR #4-10A  
API: 05-123-19595



**Photo 1.** Photo taken from the well location, facing North. Well has been plugged and abandoned on an active, multi-well location; therefore, this is a well release on an active location.