

# Final Reclamation Inspection

July 30, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-07622

Inspection Document #: 682403867

Weld County, CO

SWSW Section 14 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: 1415 CORP GAS UNIT #1  
API: 05-123-07622



**Photo 1.** Photo taken from the southern location, facing North. Well has been plugged and abandoned. Desirable vegetation was observed throughout the disturbance area but has not achieved uniform vegetative cover. Common Purslane (*Portulaca oleracea*) was observed in high densities throughout the disturbance area.

Inspection Photos  
Location Name: 1415 CORP GAS UNIT #1  
API: 05-123-07622



**Photo 2.** Photo taken from the eastern location. Photo illustrates bare ground and Common Purslane in high abundance.

Inspection Photos  
Location Name: 1415 CORP GAS UNIT #1  
API: 05-123-07622



**Photo 3.** Photo taken from the northeastern location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: 1415 CORP GAS UNIT #1  
API: 05-123-07622



**Photo 4.** Photo taken from the approximate center of location, facing North. See comments under Photo 1.